



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D4034-043
Job Sheet 183917



Part No: D4034-043

Job Qty: 1 ea

Part Name: Fwd Upper Rib Assembly



Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 9/28/18

Job Tracking No:

Due Date: 10/12/18

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: DWG REV C SHEETS 1,2 IPP RevA: new issue DD 09.11.23 verified by:EC IPP Rev:B as per dwg revA
10.03.15 verified by:EC IPP Rev:C 11.01.19 AS PER DWG REV.B DD VERF:EC IPP Rev:D 13.03.14 AS PER
DWG REV.pc1 DD VERF:JLM IPP REV:E 13.06.21 DWG REV.C DD VERF:JFS

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea	10/12/18	10/12/18	0.00	0.00	Start Up Large Fab-6		
100	Large Fab	1 pcs	10/12/18	10/12/18	0.00	0.81	Large Fab 1		
110	QC	1 pcs	10/12/18	10/12/18	0.00	0.00	QC9		
120	QC	1 pcs	10/12/18	10/12/18	0.00	0.00	QC5		
130	Packaging	1 pcs	10/12/18	10/12/18	0.00	0.00	Packaging3 Large Fab		
140	QC21-SA	1 Ea	10/12/18	10/12/18	0.00	0.00	QC21		

Part Op 100 - 1- Assemble ribs to hoop and weld as per dwg DT9564 2- Weld bushing in rib as per dwg
Descriptions: 130 - LOCATION: WA004

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D4021-7	Hoop	1 Ea (1 ea) 7	90-Start up Operation	3X5113175/4X5132097
D4021-9	Bushing	1 Ea (4 ea) 38	90-Start up Operation	5115312
D4034-1	Rib	1 Ea (1 ea) 7	90-Start up Operation	2X5131342/2X5130152/3X
D4034-3	Rib	1 Ea (1 ea) 7	90-Start up Operation	5143222 5142791

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	D4021-7	1	17	0
	D4021-9	4	60	0
	D4034-1	1	14	0
	D4034-3	1	4	0



Container No: S143618



Part: D4034-043

Job No: 183917

Serial No/Batch: S143618

Revision:

Inspector:

Exp Date:

Instructions: Various STC's

Date: 01/10/19

ind.

Plex 9/28/18 12:56 PM Dart.lajeunesse.marie

007409

DQA: _____ Date: _____

**WORK ORDER NON-CONFORMANCE / UPDATE**

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____			
Misidentified ☐	Past Due ☐				